



Hewlett Packard Enterprise Support Center Enterprise

Treiber und Software

** CRITICAL ** Systems ROMPaq Firmware Upgrade for HP ProLiant DL585 G2/DL585 G5/DL585 G6 (A07) Servers

Geben Sie ein:	BIOS - System-ROM
Version:	2011.05.02 (B)(4 Nov 2014)
Betriebssystem(e):	Asianux 3
	CentOS 5
	Citrix XenServer 4.x
	Citrix XenServer 5.x
	Debian GNU/Linux 4.0 (AMD64/EM64T)
	Debian GNU/Linux 4.0 (x86)
	Debian GNU/Linux 5.0 (AMD64/EM64T)
	Debian GNU/Linux 5.0 (x86)
	Microsoft Windows HPC Server 2008 R2
	Microsoft Windows Server 2003
	Microsoft Windows Server 2003 for 64-bit Extended Systems
	Microsoft Windows Server 2008 Essential Business
	Microsoft Windows Server 2008 R2
	Microsoft Windows Server 2008 Small Business
	Microsoft Windows Server 2008 W32
	Microsoft Windows Server 2008 x64
	Oracle Linux 5 (AMD64/EM64T)
	Oracle Linux 5 (x86)
	OS Independent
	Red Hat Enterprise Linux 3 (AMD64/EM64T)
	Red Hat Enterprise Linux 3 (x86)
	Red Hat Enterprise Linux 4 (AMD64/EM64T)
	Red Hat Enterprise Linux 4 (x86)
	Red Hat Enterprise Linux 5 Server (x86)
	Red Hat Enterprise Linux 5 Server (x86-64)
	Red Hat Enterprise Linux 6 Server (x86)
	Red Hat Enterprise Linux 6 Server (x86-64)
	Solaris 10 for x86 Systems
	SUSE Linux Enterprise Server 10 (AMD64/EM64T)
	SUSE Linux Enterprise Server 10 (x86)
	SUSE Linux Enterprise Server 11 (AMD64/EM64T)
	SUSE Linux Enterprise Server 11 (x86)
	SUSE Linux Enterprise Server 9 (AMD64/EM64T)
	SUSE Linux Enterprise Server 9 (x86)
	Ubuntu 10.04 LT (x86)
	Ubuntu 10.04 LTS (AMD64/EM64T)
	Ubuntu 9.04 (AMD64/EM64T)
	Ubuntu 9.04 (x86)
	Ubuntu 9.10 (AMD64/EM64T)
	Ubuntu 9.10 (x86)
	VMware ESX Server 3.0
	VMware ESX/ESXi 4.0
	VMware ESX/ESXi 4.1
	VMware ESX/ESXi Server 3.5

Beschreibung

This release provides updated system ROM images for the latest maintenance releases of HP DL585 G2/DL585 G5/DL585 G6 Servers.

Erweiterungen

Enhanced the System ROM flash update process to improve the reliability of System ROM updates and decrease the probability of unintended corruption of the flash part. Note: As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link:
http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Installationsanleitungen

To ensure the integrity of your download, HP recommends verifying your results with this MD5 Checksum value:

3a303a10c23f11dd47f2f9c27882677b SP68126.exe

Reboot Requirement:

Reboot is required after installation for updates to take effect and hardware stability to be maintained.

Installation:

1. Obtain a formatted USB Key media.
2. Download the SoftPaq to a directory on a system running Microsoft Windows 2000, Microsoft Windows XP, Microsoft Windows Vista, Microsoft Windows 7, Microsoft Windows Server 2003, Microsoft Windows Server 2008, or Microsoft Windows Server 2008 R2 and change to that directory.
3. From that drive and directory, execute the downloaded SoftPaq file: Simply double click on the SPxxxx.exe file and follow the installation wizard to complete the SoftPaq installation process. At the end of a successful installation of the SoftPaq a web page will automatically appear to provide you with the different methods for restoring and/or upgrading the firmware on the system.
4. After the USB Key is created, you may delete the downloaded file if you wish.
5. Insert this USB Key into the USB Key port of the system to be updated and power the system on to boot to the USB Key.

Versionshinweise

End User License Agreements:

[Hewlett-Packard End User License Agreement](#)

Upgrade Requirement:

Critical - HP requires users update to this version immediately.

Important:**Important Notes:**

As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link: http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Version 2011.05.02(B) has been signed with the new digital signature and replaces version 2011.05.02(A). The actual firmware contained within version 2011.05.02(B) did not change as compared to version 2011.05.02(A) and therefore it is not necessary to upgrade if version 2011.05.02(A) has already been installed.

Deliverable Name:

HP ProLiant DL585 G2/G5/G6 System ROM - A07

Release Date:

05/02/2011

Last Recommended or Critical Revision:

05/02/2011

Previous Revision:

04/30/2010

Firmware Dependencies:

None

Enhancements/New Features:

Enhanced the System ROM flash update process to improve the reliability of System ROM updates and decrease the probability of unintended corruption of the flash part. Note: As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link: http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Problems Fixed:

Added latest product names of optional expansion cards for display in the ROM-Based Setup Utility (RBSU).

Known Issues:

None

Fixes**Upgrade Requirement:**

Critical - HP requires users update to this version immediately.

Important Notes:

As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link: http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Version 2011.05.02(B) has been signed with the new digital signature and replaces version 2011.05.02(A). The actual firmware contained within version 2011.05.02(B) did not change as compared to version 2011.05.02(A) and therefore it is not necessary to upgrade if version 2011.05.02(A) has already been installed.

Firmware Dependencies:

None

Problems Fixed:

Added latest product names of optional expansion cards for display in the ROM-Based Setup Utility (RBSU).

Known Issues:

None

Wichtig**Important Notes:**

As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link: http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Version 2011.05.02(B) has been signed with the new digital signature and replaces version 2011.05.02(A). The actual firmware contained within version 2011.05.02(B) did not change as compared to version 2011.05.02(A) and therefore it is not necessary to upgrade if version 2011.05.02(A) has already been installed.

Deliverable Name:

HP ProLiant DL585 G2/G5/G6 System ROM - A07

Release Date:

05/02/2011

Last Recommended or Critical Revision:

05/02/2011

Previous Revision:

04/30/2010

Firmware Dependencies:

None

Enhancements/New Features:

Enhanced the System ROM flash update process to improve the reliability of System ROM updates and decrease the probability of unintended corruption of the flash part. Note: As enhancing the flash upgrade process requires modifications to both the System ROM and the flash update utility, the System ROM revision cannot be downgraded with the flash components available on the HP Support site after updating to this revision of the System ROM. A customer can downgrade the System ROM by creating a new flash component with the older System ROM revision as indicated in Advisory C02838375 available at the following link:
http://h20000.www2.hp.com/bizsupport/TechSupport/Document.jsp?locale=en_US&objectID=c02838375

Problems Fixed:

Added latest product names of optional expansion cards for display in the ROM-Based Setup Utility (RBSU).

Known Issues:

None

Versionsprotokoll

Version:2011.05.02 (B) (4 Nov 2014)
Version:2010.04.30 (A) (4 May 2010)
Version:2009.12.14 (A) (12 Jan 2010)
Version:2009.07.28(A) (24 Aug 2009)
Version:2009.05.07(A) (27 May 2009)
Version:2009.03.11 (B) (20 Apr 2009)
Version:2008.09.27 (B) (15 Apr 2009)
Version:2008.06.27 (A) (1 Aug 2008)
Version:2008.03.28 (A) (9 Apr 2008)
Version:2008.02.20 (A) (7 Apr 2008)
Version:2007.11.21 (A) (27 Feb 2008)
Version:2007.09.24 (A) (7 Dec 2007)
Version:2007.02.27 (A) (4 Apr 2007)
Version:2007.01.08 (A) (23 Jan 2007)
Version:2006.12.02 (A) (2 Jan 2007)
Version:2006.09.13A (10 Oct 2006)

Haftungsausschluss: Produkte, die vor dem 1. November 2015 (Datum der Trennung der Hewlett-Packard Company in Hewlett Packard Enterprise Company und HP Inc.) verkauft wurden, tragen möglicherweise ältere Produktnamen und Modellnummern, die von den aktuellen Modellen abweichen.